


☐ Pending

☒ Active

- ☒ L1: (526) (296/214).CCLS.
- ☒ L2: (176) (296/219).CCLS.
- ☒ L3: (3) (("6179373") or ("5558394") or ("4274672")).PN.
- ☒ L4: (0) (B60J003/00.ipc.).CCLS.
- ☒ L5: (1847) B60J003/00.ipc.
- ☒ L6: (207) 15 and roof
- ☒ L7: (2) 16 and loop
- ☒ L8: (48) 15 and roof with panel
- ☒ L9: (1556) b60j007/00.ipc.
- ☒ L11: (1) 110 and loop
- ☒ L10: (82) 19 and sunshade
- ☒ L12: (632) (160/270-273.1).CCLS.
- ☒ L13: (371) (160/273.1).CCLS.
- ☒ L14: (4) ("0436900" | "1281571" | "3768540" | "4792178").PN.
- ☒ L15: (4) 6179373.URPN.
- ☒ L16: (399) (296/98).CCLS.
- ☒ L17: (0) ("116andlamb.in.").PN.
- ☒ L18: (0) ("116andlamb").PN.
- ☒ L19: (4) 116 and lamb.in.

☒ Failed

- ☒ (0) ("296/214.ccls.-296/224.ccls.").CCLS.
- ☒ (0) ("296/\$.ccls.").CCLS.
- ☒ (0) ("296/\$.ccls.").CCLS.

 ☐ Plurals

 Default open ☒ Highlight all hit terms initially

116 and lamb.in.

☒ Drafts

☐ Pending

☒ Active

☐ Failed

☒ Saved

☒ Favorites

☒ Tagged (15)

☐ UDC

☐ Queue

☐ Trash

	U	I	Document ID	Issue Dat	Page	Title	Current
1	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 20030006630	20030109	16	Sunshade for a motor vehicle roof	296/214
2	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 6186587 B1	20010213	10	Blind arrangement for vehicles	296/214
3	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 6179373 B1	20010130	10	Sunshade for a vehicle	296/214
4	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 1893350 A	19330103	4	Motor vehicle body having collapsible head	296/219
5	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 1893349 A	19330103	6	Motor vehicle body having collapsible head	296/219
6	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 1738060 A	19291203	9	TEXT NOT AVAILABLE	296/219
7	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 6685251 B2	20040203	11	Retractable cover system for open top end	296/100.C
8	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 4792178 A	19881220	9	Truck tonneau cover assembly	296/98
9	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 1281571 A	19181015	3	TEXT NOT AVAILABLE	296/138
10	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 6119758 A	20000919	25	Closure device with a flexible screen	160/273.1
11	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 5123474 A	19920623	9	Roll-up closure device	160/310
12	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 3051232 A	19620828	3	Retractable cover assembly and draw cord	160/368.1
13	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 0722653 A	19030310	4	TEXT NOT AVAILABLE	160/28
14	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 4563034 A	19860107	6	Retractable truck bed cover for pick-ups	296/98
15	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 3979782 A	19760914	6	Swimming pool cover	4/502

EAST - [golf cart:2]

FileViewEditToolsWindowHelp

Pending

Active

L1: (526) (296/214).CCLS.

L2: (176) (296/219).CCLS.

L3: (3) (("6179373") or ("5558394") or ("4274672")).PN.

L4: (0) (B60J003/00.ipc.).CCLS.

L5: (1847) B60J003/00.ipc.

L6: (207) 15 and roof

L7: (2) 16 and loop

L8: (48) 15 and roof with panel

L9: (1556) b60j007/00.ipc.

L11: (1) 110 and loop

L10: (82) 19 and sunshade

L12: (632) (160/270-273.1).CCLS.

L13: (371) (160/273.1).CCLS.

L14: (4) ("0436900" | "1281571" | "3768540" | "4792178").PN.

L15: (4) 6179373.URPN.

L16: (399) (296/98).CCLS.

L17: (0) ("116andlamb.in.").PN.

L18: (0) ("116andlamb").PN.

L19: (4) 116 and lamb.in.

Failed

(0) ("296/214.ccls.-296/224.ccls.").CCLS.

(0) ("296/\$.ccls.").CCLS.

(0) ("296/\$.ccls.").CCLS.

SearchListBrowseQueue

DBsPlurals

Default oper Highlight all hit terms initially

116 and lamb.in.

Drafts

Pending

Active

Failed

Saved

Favorites

Tagged (15)

UDC

Queue


Trash

	Type	L #	Hits	Search Text	DBs	Time Stam	Comment	Error
6	BRS	L6	207	15 and roof	DERW ENT	2004/09/2 0 08:45		
7	BRS	L7	2	16 and loop	DERW ENT	2004/09/2 0 08:45		
8	BRS	L8	48	15 and roof with panel	DERW ENT	2004/09/2 0 08:47		
9	BRS	L9	1556	b60j007/00.ipc.	DERW ENT	2004/09/2 0 08:47		
10	BRS	L11	1	110 and loop	DERW ENT	2004/09/2 0 08:47		
11	BRS	L10	82	19 and sunshade	DERW ENT	2004/09/2 0 08:57		
12	IS&R	L12	632	(160/270-273.1).CCLS.	USPA T	2004/09/2 0 08:58		
13	IS&R	L13	371	(160/273.1).CCLS.	USPA T	2004/09/2 0 09:19		
14	BRS	L14	4	("0436900" "1281571" "3768540"	USPA T	2004/09/2 0 09:00		
15	BRS	L15	4	6179373.URPN.	USPA T	2004/09/2 0 09:01		
16	IS&R	L16	399	(296/98).CCLS.	USPA T	2004/09/2 0 09:19		
17	IS&R	L17	0	("116andlamb.in.").PN	USPA T	2004/09/2 0 09:19		
18	IS&R	L18	0	("116andlamb").PN.	USPA T	2004/09/2 0 09:20		
19	BRS	L19	4	116 and lamb.in.	USPA T	2004/09/2 0 09:20		

116

Details

HTML



```

(0) ("296/214.ccls.-296/224.ccls.").CCLS.
(0) ("296/$.ccls.").CCLS.
(0) ("296/$.ccls.").CCLS.
(0) ll and (stop adj2 block))
(0) M.E.D.
(0) ("200/$.ccls.").CCLS.
(0) ("188/$.ccls.").CCLS.
(0) ("296/$.ccls.").CCLS.
(4) golf near2 cart with solar near2 cell$
(0) 296/110.02.ccls.-296/100.05.ccls.
(0) ("(4662115or4919473or5536060or5924760o

```

Trash

	U	1	Document ID	Issue Dat	Page	Title	Current (
1	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 20030006630	20030109	16	Sunshade for a motor vehicle roof	296/214
2	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 6186587 B1	20010213	10	Blind arrangement for vehicles	296/214
3	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 6179373 B1	20010130	10	Sunshade for a vehicle	296/214
4	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 1893350 A	19330103	4	Motor vehicle body having collapsible head	296/219
5	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 1893349 A	19330103	6	Motor vehicle body having collapsible head	296/219
6	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 1738060 A	19291203	9	TEXT NOT AVAILABLE	296/219

EAST - [golf cart:2]

File View Edit Tools Window Help

Pending

Active

L1: (526) (296/214).CCLS.

L2: (176) (296/219).CCLS.

L3: (3) (("6179373") or ("5558394") or ("4274672")).PN.

L4: (0) (B60J003/00.ipc.).CCLS.

L5: (1847) B60J003/00.ipc.

L6: (207) 15 and roof

L7: (2) 16 and loop

L8: (48) 15 and roof with panel

L9: (1556) b60j007/00.ipc.

L11: (1) 110 and loop

L10: (82) 19 and sunshade

Failed

(0) ("296/214.ccls.-296/224.ccls.").CCLS.

(0) ("296/\$.ccls.").CCLS.

(0) ("296/\$.ccls.").CCLS.

(0) 11 and (stop adj2 block))

(0) M.E.D.

(0) ("200/\$.ccls.").CCLS.

(0) ("188/\$.ccls.").CCLS.

(0) ("296/\$.ccls.").CCLS.

(4) golf near2 cart with solar near2 cell\$

(0) 296/110.02.ccls.-296/100.05.ccls.

(0) ("(4662115or4919473or5536060or5924760or5944373or6068327).pn.")

Search

List

Browse

Queue

DBs

Plurals

Default oper Highlight all hit terms initially

19 and sunshade

Drafts

Pending

Active

Failed

Saved

Favorites

Tagged (6)

UDC

Queue

Trash

	Type	L #	Hits	Search Text	DBs	Time Stam	Comment	Error I
1	IS&R	L1	526	(296/214).CCLS.	USPA	2004/09/2		
2	IS&R	L2	176	(296/219).CCLS.	USPA	2004/09/2		
3	IS&R	L3	3	(("6179373") or ("5558394") or ("4274	USPA	2004/09/2		
4	IS&R	L4	0	(B60J003/00.ipc.).CCL	DERW	2004/09/2		
5	BRS	L5	1847	B60J003/00.ipc.	ENT	2004/09/2		
6	BRS	L6	207	15 and roof	ENT	2004/09/2		
7	BRS	L7	2	16 and loop	DERW	2004/09/2		
8	BRS	L8	48	15 and roof with panel	ENT	2004/09/2		
9	BRS	L9	1556	b60j007/00.ipc.	DERW	2004/09/2		
10	BRS	L11	1	110 and loop	ENT	2004/09/2		
11	BRS	L10	82	19 and sunshade	DERW	2004/09/2		

NUM